

Norman H. Bangerter, Governor Dee C. Hansen, Executive Director Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION 9:00 am -	DATE & TIM 11:00 am	E: _	1/22/87	
Permittee and/or Operators Name: Genwal Coal				
Rusiness Address: P.O. Rox 1201 Hunington.	tah 84527			
Business Address: P.O. Box 1201 Hunington, U Mine Name: Crandall Canyon Permit Number:	ACT/015/	032		
Type of Mining Activity: Underground X Sur	face 0	ther	•	
County: Emery				
Company Official (s): Wayne Douglas				
State Official(s): Dave Lof and Randy Harden				
Partial: X Complete: Date of Last	. Inspectio	n: D	ecember	18, 1986
Weather Conditions: Clear and Cold, Ground Fi	rozen, Appr	ox 8	inches s	now.
Acreage: Permitted 80 Disturbed 9.7 Regrad	dedSe	eded	Bon	nded <u>9.7</u>
Enforcement Action: NOV N87-4-1-1				
COMPLIANCE WITH PERMITS AND PER	FORMANCE S	TANDA	RDS	
	YES	<u>NO</u>	<u>N/A</u>	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	7		
3. TOPSOIL	$\overline{(}$			\overline{C}
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	$\overline{(X)}$			<u>(X)</u>
c. SEDIMENT PONDS AND IMPOUNDMENTS		7	<u> </u>	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)		()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	(<u>) ()</u>	<u>(X)</u>
f. EFFLUENT LIMITATIONS	()	(()	$\frac{\langle \cdot \cdot \rangle}{\langle \cdot \cdot \rangle}$
5. EXPLOSIVES	()	($\frac{1}{2}$	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)		()	(X)
7. COAL PROCESSING WASTE	. ()		/ //	\ \ \ \ \ \ \
8. NONCOAL WASTE	. ()		<u> </u>	
9. PROTECTION OF FISH, WILDLIFE AND	- ()	,	١ ()	()
RELATED ENVIRONMENTAL VALUES	- }	} 	$\frac{1}{2}$	}
10. SLIDES AND OTHER DAMAGE	- } 	}	5 ~ ~ 	}
11. CONTEMPORANEOUS RECLAMATION 12. BACKFILLING AND GRADING	- } 	}	5 7 5	`
12. BACKFILLING AND GRADING 13. REVEGETATION	- } 	}	5 	\overrightarrow{C}
14. SUBSIDENCE CONTROL	- } 	}	\(\) \(\)	```
15. CESSATION OF OPERATIONS	- ` 	\	5 7	$\overrightarrow{(}$
16. ROADS			<u></u>	
a. CONSTRUCTION	_ ()	() ()	()
b. DRAINAGE CONTROLS	$-\frac{1}{(X)}$	\	5 ()	$\overline{(X)}$
c. SURFACING	- ()	(5 ()	()
d. MAINTENANCE	$-\frac{1}{(X)}$	(5 (<u>(X)</u>
17. OTHER TRANSPORTATION FACILITIES	_ (() ()	()
18. SUPPORT FACILITIES				
LITTLITY INSTALLATIONS	_ ()	() ()	()

INSPECTION REPORT (continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION 1/22/87

(Comments are Numbered to Correspond with Topics Listed Above)

- 4.b. DIVERSIONS Diversion UD-1 does not have an outlet extension piece installed as per the design of the structure. The Operator should install this section of the culvert prior to the commencement of spring runoff.
- 4.d OTHER SEDIMENT CONTROL MEASURES Snow windrows were left along the sides of the roadways which would allow the retention of water along the roads during snowmelt. Conditions at the site indicated that no snowmelt had occurred since the windrows were developed. The operator was requested to provide cutouts along the windrows in order to allow snowmelt to leave the roads and not channel along the roadway during snowmelt. Upon leaving the site, the Operator had commenced providing cutouts along the snow windrows to allow proper drainage.
- 4.e. SURFACE AND GROUNDWATER MONITORING The Operator was asked if the groundwater monitoring well had been drilled which was a commitment in the approved mining and reclamation plan. Mr. Douglas indicated that he personally had no knowlege of the well and indicated that no such well had been drilled on the site. Upon further review it was determined that the operator was out of compliance with section 7.1.6 Groundwater Monitoring Plan, pages 7-33a of the MRP dated 6/10/86. NOV N87-4-1-1 was issued, requiring that the monitoring well which was to be drilled from the surface facilities area into the Starpoint sandstone be completed on or before March 2, 1987.
- 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL Sediment pond cleanout materials are found on the coal loadout pad which is in accordance with the approved temporary storage location as identified in the mining and reclamation plan. The drainage ditch from the road leads to the toe of the sediment pond material. Because the ground is frozen in the area, the operator cannot effectively regrade the ditch to circumvent the material. It is recommended that when ground conditions improve that the ditch be regraded so as not to allow the material to be eroded and end up back in the sediment pond.
- 8. NONCOAL WASTE The area including the generator and oil and fuel storage facilities was inspected and no excessive amount of oil or fuel was found outside of the containment area.
- 16.b. and d. ROADS DRAINAGE CONTROLS Some of the inlet structures of the culverts were found to be partially blocked by snow windrows on the site. The Operator was requested to improve the drainage into the culvert inlets by cutting out the windrows leading into the culverts.

Сору	of this Report:		
	Mailed to:	Donna Griffin - OSM	
	Given to:	Sue Linner and Joe Helfrich - DOGM	

Inspectors Signature and Number: | Pull Helmon #13 Date: 3-4-87